



- Pin 9 - 0v Ground
- Pin 8 - No Connect
- Pin 7 - 50/60Hz
- Pin 6 - Calibrate
- Pin 5 - No Connect
- Pin 4 - PWM
- Pin 3 - SDA
- Pin 2 - SCL
- Pin 1 - +5v